

The owner of this private golf course spent a lot of time and money on special seeds and nutrients in his attempts to renew the putting surface of the green to a nice, lush, smooth putting surface.

The root system of the two mature trees nearby were absorbing all the nutrients and caused damage to the putting surface of the green.

The solution was to install **Biobarrier**.

- A trench was dug to a depth of 24”.
- Biobarrier was positioned vertically in the trench.
- Plastic pegs supplied with each roll were used to secure the Biobarrier in place..
- Soil that was removed when digging the trench was reused to fill the trench cavity.



Biobarrier's performance is guaranteed for 15 years, but expect this period to last 25 and perhaps 30 years.