



BIOBARRIER®

**ROOT CONTROL**

PROJECT: Parc Soucy, Delson, QC

PROBLEM: Poplar trees 8” in diameter. Root system invading private properties adjacent to park.

SOLUTION: Biobarrier was placed vertically in a trench 30” deep. The trench was dug parallel to the fence the full length of the property. The trench was then backfilled and compacted.



Biobarrier’s performance is guaranteed by the manufacturer for **15** years, but you can expect it to last for **25** and even **30** years!