


Tree roots can cause extensive damage to foundations (cracks, leaks), walkways and driveways (cracks, protrusions).

A homeowner had been experiencing these problems to his driveway and sidewalk due to the mature trees on his property.

They did NOT want to cut down the trees. The solution they opted for was **Biobarrier**.

- *General view of property and driveway showing mature trees.*
- *A trench was dug to a depth of 36”.*
- *Biobarrier was positioned vertically in the trench.*
- *Plastic pegs supplied with each roll were used to secure the Biobarrier in place.*
- *Soil that was removed when digging the trench was reused to fill the trench cavity.*



Biobarrier's performance is guaranteed for 15 years, but expect this period to last 25 and perhaps 30 years.