

TREE ROOTS INVADING A PLAYGROUND

The ground surface of this playground was covered with rubber mats. Tree roots from nearby trees began invading the playground and pushing up the rubber mats.



In order to control the invasion of the tree roots, a trench (one meter deep) was dug along the fence and Biobarrier was set in place making sure that it would extend up to the surface at ground level.



After the backfill was completed, the rubber mats which covered the entire playground were put back in place.



Biobarrier's performance is guaranteed by the manufacturer for **15** years, but you can expect it to last for **25** and even **30** years!