

**SWIMMING POOL
AND LANDSCAPING**

This homeowner had a pool installed and landscaping done. Once completed, everything looked perfectuntil the end of the summer when weeds started appearing through the decorative stones in the landscaped area and around the pool.




After consultation with a landscaping architect, Biobarrier was recommended to fully control the weeds.

The first step was to remove the existing stones.



In the recreational area, Biobarrier was set in place and covered with 3" of stones.



The same process was implemented for the remainder of the pool perimeter.



Biobarrier's performance is guaranteed by the manufacturer for 15 years, but you can expect it to last for 25 and even 30 years!