



BIOBARRIER®



SWIMMING POOL London, ON

Every year, trees are needlessly cut down because their roots intrude into foundations, driveways, sidewalks and swimming pools. Repairs can be quite extensive and expensive. Often, the first thing that is done is to cut down the tree.

The backyard is surrounded by mature maple and willow trees. In order to prevent the tree roots from damaging the new swimming pool, Biobarrier was the product of choice.

Save the trees, save your investment!

As you can see below, the location of the pool was sketched out prior to excavation.



The site was excavated and Biobarrier was set in place at the base of the pool and brought up on the exterior side top position of the structural metal panels.



Biobarrier's performance is guaranteed by the manufacturer for 15 years, but you can expect it to last for 25 and even 30 years!