

Vinegar Tree Roots Damaging Pool Liners

Many residents of the municipality of Delson (Quebec) were complaining about the intrusion of roots from Vinegar trees surrounding their property. At one point, the roots were perforating swimming pool liners.

Since the trees are located on public property, the municipality of Delson had to find a permanent solution to the problem.....The only solution was to install **Biobarrier**.


What is a Vinegar Tree?

The Vinegar Tree (*Rhus Typhina*) is native to North America. The leaves are a glossy dark green in the spring and summer and turns brilliant red in the fall. It is known to be drought tolerant and can also be seen in places like Africa.

Although the Vinegar Tree turns to brilliant shades of red, orange and yellow in autumn, it has a vigorous & invasive root system and should **not** be planted near pipes, foundations, interlock, asphalt paving and of course swimming pools.




A 24" deep trench was dug all along the affected properties.



Plastic pegs supplied with each roll were used to secure the Biobarrier in place.



Backfilling and compacting was done.



Biobarrier's performance is guaranteed by the manufacturer for **15** years, but you can expect it to last for **25** and even **30** years!